



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Karl Houskeeper

Inspection Report

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Thursday, November 01, 2012
Start Date/Time:	11/1/2012 6:30:00 AM
End Date/Time:	11/1/2012 11:30:00 AM
Last Inspection:	Tuesday, October 02, 2012

Inspector: Karl Houskeeper,

Weather: <u>Clear Skies, Temp. 36 Deg. F.</u> InspectionID Report Number: <u>3282</u>

Types of Operations

Reprocessing

Accepted by: jhelfric

11/29/2012

Permitee: CONSOLIDATION COAL CO
Operator: CONSOLIDATION COAL CO

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	442.50		
Total Disturbed	248.50		
Phase I			
Phase II			
Phase III			

Mineral Ownership

Other

✓ Federal ✓ Underground

State Surface

County Loadout

✓ Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the Main Office at the Emery Deep Mine. Lester Jorgensen was dispatched as the company representative for the Partial inspection of the Emery Deep Mine.

Mine is still under temporary cessation of operation.

Inspector's Signature:

-Karl R. Houskeeper

Date

Thursday, November 11,20

OIL, GAS & MINING

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Thursday, November 01, 2012

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	~		~	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓		✓	
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		V	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.t	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22	Other				

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Thursday, November 01, 2012 Page 3 of 3

2. Signs and Markers

The mine identification signs at the Main Facility and the 4th East Portal Area were observed during the partial inspection and found to be in compliance with the Utah R645 Coal Rules.

4.c Hydrologic Balance: Other Sediment Control Measures

The silt fence located near the water storage tank at the 4th East Port Area was checked and found to be functional.

5. Explosives

Some powder and caps still remain in the approved storage magazines. The magazines are properly grounded and identified with signs.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared to be stable. No visible hazards were observed.